

8

7

6






3

5) (2)(?)


- MAKE SURE THAT THE UPPER ROLLER CLEVISES DO NOT RUB ON THE TOE GUARD WHILE THE LIFT IS RAISING AND LOWERING.
- SHIPPING NOTES:
  PUT RISER BLOCKS UNDERNEATH THE LIFT SO THAT THE LIFT CAN EASILY BE REMOVED WITH A FORK TRUCK BY THE CUSTOMER.



## **5**HIS DRAWING MUST BE AT REVISION: 4C'

	2		DWG NO	Sheet 1 of 1						
REVISIONS										
REV.	DESCRIPTION		DATE	REVISED BY	ECO #					
А	ITEM 1 WAS 80006733, QTY 1. ITEM 4 WAS 80006 WIDE, PLATFORM WAS 47'' WIDE.	7/28/2014	DPM	R6612						
В	ITEM 4 WAS 80007141. ADDED ITEM 11. VERTICA LOWERED HEIGHT WAS 3-1/8".	10/21/2016	EJP	R11113						
С	REMOVED NOTE TO PAINT TOE GUARD SAFETY	YELLOW.	9/13/2017	RSE	036570					

## ZIP TIE TOEGUARD CORD TO HYDRAULIC LINE



B	11	1	ΕA	TP PF SPCL 49.00X57.50 STR ROLL U2.2					60046471		
	10		REF	HY PLUMBING SCHEM	80	80004958					
	9		REF	EL WIRING DIAG 115 AC NO XFMR					80006744		
	8	1	ΕA	EL FS UP/DN STD CONINT 892-2460-06				30	3032144		
BA	7	10	FT	el Cable 18-3 SJO				28	2800956		
	6	1	ΕA	HY HOSE ASSY FC639-04X96.00				60	60024036		
	5	1	ΕA	EL PWR CORD W/DECAL				29	2947300		
	4	1	ΕA	SA ROLLU/E 2.2 TOE GD W/ LIMIT SW ASSY					60047701		А
	3	1	ΕA	HY PU E 1P 1.0HP .48GPM .60UGAL				60	60042527		
	2	1	ΕA	HY ARR E ROLL E2.5 49.50W				60	60042455		
(A)	A      1      1      EA      BA B&L ASSY UL32-22 50.00X57.87					80	80007140				
ONS ± 1/16	ITEM NO.	QTY.	U/M		DESCRIPTION				PART NO.		
± .005 ± .01 S: ± .5° <b>PRESTO LIFTS</b>							DR AE	BS/DAP	DATE 01/1	3/14	
otherwise							СК	DATE			
ED. IONS ARE IN	5005001				063Z8 <sub>WT</sub> 457.84 LB	SCALE	1:6 <sub>MC</sub>	DDEL	•		
	TL LIFT UL32-22 STAN					D SIZE	U DWG. NC	L32-2	22 HEET 1 OF 1	C REV	
2						1					

B